









Notes: Refer to STEP


Check adhesion with plate so it is not lifted.
Clean any overhanging filament

UNLESS OTHERWISE SPECIFIED, DIMENSIONS ARE IN MILLIMETERS LINEAR = $x \pm 0.1$ $x.x \pm 0.1$ $x.xx \pm 0.01$ $x.xxx \pm 0.005$ ANGULAR = $\pm ^\circ 0.5$ DO NOT SCALE DRAWING BREAK ALL SHARP EDGES AND REMOVE BURRS	NAME		DATE	SIENCI LABS Phone: 1-855-220-1231 Address: 120 Randall Drive Unit 1B-D, Waterloo, ON N2V 1C6	
	DRAWN	SIENCI LABS	18/08/2026		
	CHECKED	JONATHAN SCHUMACHER	04/09/2026	TITLE LONGMILL MK3 LONGMILL MK3 DUST SHOE BASE AXDS-0024	
	APPROVED	Quality Assurance	04/09/2026		
	THIRD ANGLE PROJECTION		MATERIAL	FINISH	SIZE
		PETG WHITE	AS PRINTED	A	DWG NO. AXDS-0024-R3D1
		SCALE	1:2	WEIGHT	123.276 G
		SHEET	1 of 2	REV.	001

2

1

Rev. #	Changes	Date DD/MM/YYYY
1	Initial release	18/08/2026
2	Changed the material used and slight logo change	19/08/2026
3	Changes to the profile for the bristle	04/09/2026
4		



B

B

A

A

2

1